



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 24, 2013

Reviewed: 

Mine Name: Torrey Quarry	Permit Number: M/055/0016
Operator Name: Star Stone Quarries	Inspection Date: 05/22/2013
Inspector(s): Wayne Western	Time:
Other Participants: none	Mine Status: ACT
Weather Condition: 70s and clear skies	Last Inspection: August 28, 2012
Bond Renewal Date: 08/24/2016	Bond Amount: \$40,000.00
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: 2012	Acreage: 7 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The site was inactive at the time of inspection.
Bond is current.
Annual report for 2012 was submitted.
Annual fees have been paid for 2013.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Directions to Site:

Inspector's Signature _____

WHW:

cc: (OPERATOR)

John Reay, Hanksville BLM

Sue Fivecoat, Hanksville BLM

O:\M055-Wayne\M0550016-Torrey_Quarry\inspections\Insp05222013.doc



Area being quarried



Trackhoe and stacked material



Water truck



Stacked material